

Safety Notice: Yeti Convertible 2

Check webbing connections

An incident was reported where the pilot took off with the webbing incorrectly attached to the main carabiner.

Pilots should check before their next flight that the webbing on their Yeti Convertible 2 is correctly connected through all 3 webbing loops, as shown in the photo below (and also in the manual).

If you are in any doubt about how to perform this check, please contact your dealer or school.

